



Service Bulletin

73

January, 1966

SUBJECT: 876, 1076 & 1276 TRACTORS

It has been noted on subject tractors that moisture can enter the nylon bushings in the #6403 clutch pedal and create a binding condition. If this occurs the pedal will remain in the depressed position, which in turn, restricts the movement of the #6123 cam control lever assembly. The cam control lever assembly will bend when force is applied.

To correct this condition, the #5409 nylon bushings should be replaced with #6254 bronze bushings.

We also recommend that this correction be made prior to delivery of the new units.

All units after the following serial numbers will have bronze bushings installed at this location.

876	-----	193056
1076	-----	214071
1276	-----	205328

Reimbursement will be handled through normal warranty channels.

Jack D. Walton
Jack D. Walton
Service Manager

JDW:rac