



Service Bulletin

97

April 1968

Rotary Mower Changes

Models 5-1362, 5-1421, 5-1481

To insure better tractor to mower belt alignment, minor changes have been incorporated in the above mowers.

These changes are described below and are applicable when mounting these mowers on all long frame tractor models.

Model 5-1362 Mower

Bushing #1536 (3/16" long) located between idler pulley #1623 and idler cam assembly #6636 has been replaced by spacer #2138 (3/8" long). A #1536 bushing is still used between the outside of the pulley and the #6360 bracket.

Model 5-1421, 5-1481

Bushing #1967 (5/16" long) located between idler pulley #4974 and the R. H. mounting plate #6712 has been replaced by #6638 (7/16" long).

In addition to the above spacer change a 3/8" washer #920009-4 has been added to the 3/8"-16 x 1 1/4" bolt between the 3/8" lock washer and the ball bearing and pulley assembly. The addition of the washer prevents the possibility of the bolt bottoming on the #7068 cam lever.

Electro Clutch Models

For proper belt alignment the electric clutch should be positioned on the crankshaft all the way against the shoulder in the clutch bore. The clutch is secured on the shaft with two set screws.

Atwood S. Kidder

ATWOOD S. KIDDER
Customer Relations Manager