



Service Bulletin

89

December, 1967

"STREAKING" 36" ROTARY MOWERS 1966, 1967 AND EARLY 1968 MODELS

New longer blades have been developed and are now in production on current 36" Rotary Mowers. These blades are of the same design as the former blades except for length. Approximately 5/16" has been added to their overall length, which increases the overlap of the two blades. This additional overlap has proven effective in eliminating streaking prevalent under certain mowing conditions.

Streaking may be described as a narrow strip of uncut grass noticeable in the center of the newly mowed path.

New part numbers are listed below.

- 7906 18" Right hand blade
- 7907 18" Left hand blade
- 7910 Special bolt (Required on models with quadrant height control)

These new blades are available for 36" Rotary Mowers and may be substituted for the original blades whenever a complaint of streaking is encountered.

When installing the new blades the two (2) #6577 bolts that hold the wheel support assemblies to the mower deck must be changed to special bolt #7910. The #7910 bolts have a thinner head and are necessary to provide sufficient blade clearance.

A. S. Kidder
Customer Relations Manager

ASK/rr