



Service Bulletin

75

June, 1966

SUBJECT: Rotary Mowers

We have received reports of problems which are usually the result of improper mower installation. The following possibilities should be checked.

- RL-366 - Proper installation and location of quick hitch assembly. Improper installation will permit interference between the right front tire and the #6908 pulley.
- RL-426 - #4974 idler pulley should be installed in lower hole of #6712 right hand mounting plate for proper belt alignment.
- RL-486 - Install #4974 idler pulley in lower hole of 6712 right hand mounting plate if belt size will allow. On those units on which the pulley is in the upper hole, additional belt adjustment can be obtained when needed by moving pulley to lower hole.

CAUTION: Use PT-6 power take-off units only with the above units.

Jack D. Walton
Jack D. Walton
Customer Relations Manager

JDW:rac