


# Service Bulletin

62

February 16, 1965

## SUBJECT: STEERING SECTORS

It has come to our attention that the Part No. 933229 Roll Pin securing the Part No. 5627 Steering Sector to the Part No. 5639 Lower Steering Shaft occasionally works loose or shears completely.



For added strength, we recommend the installation of a Part No. 933190 (3/16 x 1 1/4) Roll Pin inside the presently used Part No. 933229 (5/16 x 1 1/4) Roll Pin.

The Part No. 933190 Roll Pin is a normal stocking item.

Very truly yours,

WHEEL HORSE PRODUCTS, INC.

*Jack*

Jack D. Walton  
Service Manager

JDW: jr