


November 1968

IGNITION SWITCHES - 1968 12HP TRACTORS


It has come to our attention that an incorrect ignition switch may be installed, by mistake, in servicing 1968 12HP Tractors.

As covered in Wheel Horse Service Bulletin #93 early model 1-6231 (Raider 12) and 1-7231 (Charger 12) tractors incorporate the model K 301S-4712B Kohler engine equipped with Starter-Generator units. These units are equipped with BATTERY IGNITION and require BATTERY ignition switches.

Later models of the 1-6231 (Raider 12) and 1-7231 (Charger 12), as outlined in Wheel Horse Service Bulletin #93, incorporate the K 301S-47147B Kohler engine equipped with BENDIX TYPE STARTER, and ALTERNATOR charging system with MAGNETO IGNITION. These units require MAGNETO ignition switches.



SWITCH No. 7572
(MAGNETO TYPE)



SWITCH No. 7263
(BATTERY TYPE)

To avoid possible damage to ignition system components and/or charging system components it is imperative that the correct replacement switch be used. THE PARTS LIST DESIGNATES ONLY THE SWITCH FOR THE LATE ENGINES.

Switch #7572 is a "MAGNETO TYPE" switch and can be identified by "B", "M", AND "S" terminals. See Drawing

Switch #7263 is a "BATTERY TYPE" switch and can be identified by the "BAT", "ST", AND "IGN" terminals. See Drawing

Atwood S. Kidder

Atwood S. Kidder
Customer Relations Manager