




# Service Bulletin

91

January, 1968

## HARD STARTING - RAIDER (9) & CHARGER 9 MODELS

It has come to our attention that some of the choke wires on the Raider 9 and Charger 9 models were connected to the incorrect hole in the carburetor choke lever. The choke wire must be connected to the hole near the center of the choke lever, as shown in the accompanying sketch. Connecting the wire to the center hole permits full closing of the choke valve.



All model tractors should be checked carefully for proper choke operation. Sharp bends and kinks in the cables should be avoided to make sure choke operation is smooth, allowing complete closing and opening of the choke valves.

*A. S. Kidder*

A. S. Kidder  
Customer Relations Manager