



Wheel Horse

Service Bulletin

65

May 4, 1965

SUBJECT: MODEL RM-425 MOWERS

In addition to the Kit #6058, covered in Service Bulletin #63, it may also be necessary to install a Kit #6060 to prevent "V" belt damage.

In certain cases, there is a harmonic vibration caused at various engine speeds which can result in the main drive belt (#1599) jumping off the pulley. The Kit #6060 will eliminate this condition.

- I. Kit #6060 is available through your distributor free of charge.
- II. Flat labor rate for repair is \$3.50.

This kit is standard equipment on all mowers after serial number 144661.

Jack D. Walton
Jack D. Walton
Service Manager

JDW:jr