




# Service Bulletin

82

December, 1966

## L-107 AND L-157 LAWN RANGER

Scattered reports have been received indicating interference of the #6324 mower hanger link when raising the mower to the travel position. Should this problem be experienced, it may be corrected by removing the two front mower links #6324, and turning them 180°, end for end, as pictured below, and reassembled.



INCORRECT

CORRECT

The short end and the bend should be downward.

*Jack D. Walton*  
Jack D. Walton  
Customer Relations Manager

JDW:rac