



Service Bulletin

48

November 8, 1963

TO OUR DEALERS AND DISTRIBUTORS

SUBJECT: CLUTCHING EFFECTIVENESS (MODEL 953)

Due to a change in the mold which was used by our supplier to manufacture the Part Number 1592 V-Belts, a few of the Model 953 tractors were shipped with short V-Belts.

If you are experiencing a clutching problem, even though you have completed the adjustments as listed on the Model 953 instruction sheet, (Supplement Number 1), we suggest that you replace the drive belt with a Part Number 1592-A V-Belt. This part number is stamped on the V-Belt itself. The number on the sleeve has not been changed.

All Part Number 1592 V-Belts in your stock, which are not stamped with the "A", should be returned to the factory for inspection.

Jack D. Walton
Jack D. Walton
Service Manager

JDW:csu