



Service Bulletin



September 22, 1965

Subject: WHEEL-A-MATIC TRACTORS

A leaking condition has been experienced on some Wheel-a-Matic transmissions in the area of the cam block support casting or the serial number plate.

To correct this condition we have available #6066 trunion gasket repair kit. Important!! The complete kit must be installed on model 875 and 1075 tractors to maintain proper trunion shaft tolerances.

1. #6066 kits are available through your distributor on a no charge basis.
2. Flat labor rate for warranty repair, \$7.00.

A Wheel-a-Matic repair manual was recently mailed to all registered manual holders. We strongly urge you to use this manual and related service bulletins to repair transmissions in the field. Repairs, however, must be confined to the areas covered in these publications. The following Service Bulletins should be recorded in the back of the Wheel-a-Matic manual in the space provided for future reference, #56, #62, #64, #67, and #68.

This bulletin supercedes bulletins #56 and #67.

Jack D. Walton
Jack D. Walton
Service Manager

JDW:rac