



Service Bulletin


92

January, 1968

8-4111 HYDRAULIC LIFT

Foot rest bracket #7675 has been replaced with an improved bracket #8007. The improved bracket provides additional clearance for the hydraulic lift cylinder rod.

When installation of the new bracket is made on early model tractors the left hand foot rest must be drilled. The new bracket may be used as a template for the drilling operation, as shown in the accompanying sketch.



A. S. Kidder

A. S. Kidder
Customer Relations Manager